

GREEN POWER

“THE ORIGINAL AND STILL THE BEST GREEN CLEANER/DEGREASER”

Powder dissolves instantly. Cleans and strips away wax, silicone, flux, coolants, oil, paints, hydro-carbons, etc. Designed to separate oils and grease for weir bar, oil skimmers and coalescers faster. **Minimizes toxic waste removal.** Brightens aluminum, brass and copper. Use cold or hot. **SAFE for ALL brands** of aqueous parts washers, deburring, ultrasonics, floor scrubbers, pressure and steam cleaners. Low foam and free rinsing. Works in hard, soft and deionized water.

NO PHOSPHATES ● NO VOCs ● RUST INHIBITED

“THE ENVIRONMENT’S CHOICE” WEB SITE: www.greenpowerchemical.com

FEATURES:

- Extra Heavy Duty Industrial Strength Degreaser
- Safe for Use on All Ferrous and Non-Ferrous Surfaces
- Safe for Oxygen Service Equipment Cleaning
- Designed for Hand and Mechanical Applications

BENEFITS:

- Replaces Acetone, Mek, Mineral Spirits , Trichloroethane, Solvent Based Pre washing

PRODUCTION CLEANING OF - MIX RATIO/GALLON OF WATER: COLD OR HOT

- | | |
|---|---|
| • Pre-Clean: Plating, Powder Coating & Painting. . . 1/2 to 3 oz. | • Floor Scrubbing Machines 1 to 3 oz. |
| Aircraft, Trains, Truck, Bus & Construction | • Aqueous Parts washer, Ultrasonic. 1 to 3 oz. |
| Equipment Exteriors 1 to 4 oz. | • Aqueous Parts washer, Air Agitation or |
| Optical Lens Cleaning – Replaces Perc Etc . . 1/2 to 4 oz. | • High Pressure Nozzles. 1/2 to 3 oz. |
| Wax Removal 2 to 3 oz. | • Transmission/Engine 2 to 5 oz. |
| Lab Glassware Cleaner 1/2 to 1 oz. | • Dairy/Meat Equipment 2 to 4 oz. |
| Flush Paint from Paint Lines 2 to 3 oz. | • Boats, Exterior Fiberglass. 1 to 4 oz. |
| Cutting, Quenching, Light Oils, Hydro Carbons. 1 to 3 oz. | • Boats, Steel, Aluminum Exterior & Hull Flush . . 2 to 5 oz. |
| Aluminum 1 to 3 oz. | • Machine and Surface Wipe Down 1 to 3 oz. |
| Steel 2 to 3 oz. | • Aluminum, Vinyl Siding and Plastics 1/2 to 2 oz. |
| Fabrics, Clean and Brighten. 1/2 to 2 oz. | • Asphalt, Sealed, Terrazzo & Tile Floors. . . . 1/4 to 2 oz. |
| Flux Removal 1/2 to 3 oz. | • Floors, Steel and Concrete 2 to 5 oz. |
| Fiberglass, resins, hand & brush, cleanup. 1 to 3 oz. | • Oxygen Service Equipment 1/4 to 1 oz. |

AVOID CONTACT WITH SKIN AND EYES. **FIRST AID:** FLUSH EYES WITH PLENTY OF WATER FOR AT LEAST 15 MINUTES, OCCASIONALLY LIFTING THE UPPER AND LOWER EYE LIDS. GET MEDICAL ATTENTION. **SKIN:** FLUSH CONTAMINATED SKIN WITH WATER. GET MEDICAL ATTENTION IF IRRITATION PERSISTS. **INHALATION:** IF NEEDED GO TO FRESH AIR INGESTION: IF SWALLOWED DO NOT INDUCE VOMITING WHILE CONSCIOUS GIVE PLENTY OF WATER. GET MEDICAL ATTENTION AT ONCE. **IN CASE OF LARGE SPILL:** SWEEP UP PRODUCT AND DEPOSIT IN SEALABLE CONTAINER **TO PREVENT HARDENING OF GREEN POWER,** CLOSE LID TIGHTLY AND STORE IN DRY AREA. **FOR USE BY TRAINED INDUSTRIAL PERSONNEL.** Contains: Sodium carbonate CAS # 5968-11-6, Sodium Metasilicate CAS # 6834-92-0, Ethoxylated Alcohol CAS # 68439-46-3 Tetra sodium E.D.T.A., CAS # 64-02-8

USDA APPROVED, NO VOCs! HMIS RATINGS: Health: 1 Flammability 0 Reactivity 0

HOPATCONG*ROSELLE*STANHOPE* NEW JERSEY COUNTRY: U.S.A. PLANET: EARTH - GALAXY: MILKY WAY

800-932-9371

973-770-5600



57lbs.
GHS07



Made in the USA

SCAN FOR SDS!



1	HEALTH
0	FLAMMABILITY
0	REACTIVITY
[E]	PPE

4. Severe Hazard
3. Serious Hazard
2. Moderate Hazard
1. Slight Hazard
0. Minimal Hazard